Update Instructions for MLP31-W Wireless WAN driver

[Precaution]

Before updating the driver, you should

- Sign in as the administrator account.
- Terminate virus protection program and alike. (Restart them after finishing updating MLP31-W Wireless WAN driver.)
- Connect AC Adaptor and fully charged battery.
- Disconnect networks (wired and wireless). (Except when you download the program.)
- Disconnect all peripheral equipment.

[Summary of installation procedure]

1. Download and extract the program for updating MLP31-W Wireless WAN driver
2. Update MLP31-W Wireless WAN driver
3. Confirm the completion of updating

KEEP THESE STEPS STRICTLY, OR MALFUNCTION MAY BE CAUSED.

[Procedure]

1. Download and extract the program for updating MLP31-W Wireless WAN driver.

(1) Download the program for updating MLP31-W Wireless WAN driver.
(2) Double click the downloaded program. Click [Yes] if "User Account Control" window appears.
(3) Read the "License Agreement", and click [Yes].
(4) Confirm the destination folder (default is "c:\util2\drivers\wwan_20250728_US-FW_installer"), and click [OK].
(5) Wait until files are extracted. The folder in which update files are extracted will be automatically opened on completion.

2. Update MLP31-W Wireless WAN driver

(1) Right click or touch and hold [Pinstall.bat] and click [Run as administrator]. Click [Yes] if "User Account Control" window appears.
(2) Wait until Command Prompt closes automatically. (It takes over 5 minutes.)
(3) After updating MLP31-W Wireless WAN driver, restart the computer.

3. Confirm the completion of updating

- Confirm the version of Firmware is " T77W968.F1.0.0.5.3.xx.xxx.053 ".
  (1) (Win11) Open Windows – Settings – Network&internet – Cellular – Mobile operator settings.
  (Win10) Open Windows – Settings – Network&Internet – Cellular – Advanced options.
  (2) Confirm the Firmware version is " T77W968.F1.0.0.5.3.xx.xxx.053 ".